

Matt Burney
(317)645-6960
matt@spokecount.com

PO Box 525
Springfield, OR 97477

Metal Fabrication For the Woodworker with Matt Burney April 15-19, 2019

Tool List

Students need to bring:

4-1/2" angle grinder
5 4-1/2" cut-off wheels, a grinding wheel, 60 grit flap disc
4-1/2" flexible backing pad and assortment of grits of resin fiber discs
Metal calipers (vernier, or digital)
Center punch
Pliers with side cutters
Safety glasses
Hearing protection
Welding helmet (auto darkening highly recommended)
Cotton or flame resistant long-sleeved clothing (denim shirts and jeans work great)
Close toed, all-leather shoes
All leather work gloves and/or MIG welding gloves
Sharpie (fine point)
Mason's chisel (Dasco 1.5 inch works great)
Ball peen hammer
At least 2 steel clamps (Irwin 11SP is my favorite), but regular C-clamps are fine.

Optional:

Your personal welder (220 V, single phase, CO2/Argon tank)
TIG welding gloves
Mill files