

Matt Burney
(317)645-6960
matt@spokecount.com

PO Box 525
Springfield, OR 97477

Welding & Cutting Metal with MIG, TIG & Plasma
with Matt Burney
April 13-14, 2019

Tool List:

Students need to bring:

4-1/2" angle grinder
4-1/2" cut-off wheel, a grinding wheel, 60 grit flap disc that fit the angle grinder
Pliers with side cutters
Safety glasses
Hearing protection
Welding helmet (auto darkening highly recommended)
Cotton or flame resistant long-sleeved clothing (denim shirts and jeans work great)
Close toed, all-leather shoes
All leather work gloves and/or MIG welding gloves
Mason's chisel (Dasco 1.5 inch works great)
Ball peen hammer
At least 2 steel clamps (Irwin 11SP is my favorite), but regular C-clamps are fine.

Optional:

Your personal welder (220 V, single phase, CO2/Argon tank)
TIG welding gloves